

# LArIAT DAQ Status Update



## Observations and Issues:

- Successfully ran full DAQ 1.0 during late summer beam
- Integrated DAQ 1.0 into ArtDag, ready to “go” (John, Brian) as standard ops for next run
- In general, each individual component (V1740s, V1751, V1495, WUT, W/C TDC) of readout works as expected
  - *Except*, During beam running, WUT’s 16  $\mu$ sec pipeline frequently overflowed at 128 (unphysical) hits
  - In-time wave forms of same TOF signals digitized on V1751 looked OK!
  - Cannot reproduce problem without beam
- Analysis of beam data ongoing (Johnny, Pawel)
- Would benefit from short beam running before holidays

# LArIAT DAQ Status Update




## Correlating Data:

- Remember each readout system has their own clock, and we have fast and slow triggers
- For data to be useful, we must use all components
- Synchronize every spill via reset at \$00
- Rely on knowledge of clock frequencies to correlate data
- Results (Johnny) :
  - WUT vs. V1751 identical TOF inputs  $\sim 1 \mu\text{sec}/\text{sec}$  drift (!)
  - W/C TDC vs. V1751  $\sim 28.8 \mu\text{sec}/\text{sec}$  drift (!!)
  - V1740 in progress, more beam would help
- Good news: Correlation is possible
- Not as good news: We will have to correct absolute times


# Drift During One Spill ( ~ four seconds)

Run 2984, spill 4



12 / 14

# Spill Drift Over One run – ~30 minutes



# LArIAT DAQ Status Update



## Future Plans:

- D2S cards will be housed in separate 6U crate
  - Have ERNI cables finally! (feed V1740s)
  - Need to rearrange DAQ racks to make room
- Randy and Herr Doktor Heilige Johann working on data file handling: SAM book-keeping, long term storage (see previous week talk)
  - Need to store meta-data like DAQ's XML config files
- Data acquisition software mostly complete
- Will incorporate front-end electronics configuration control soon (Jonathan, Andrew)
- Development of online monitoring is ongoing (Pawel, Johnny)
  - Input from experts always a help here