

Kester 44 Rosin Flux Residue (PSL_005, electronic board)

7/Jun/2016 – 8/Jun/2016



Note: When we removed the sample from MTS, we noticed that a cover layer near the soldering was a bit ruined (see picture on left). Parts of that ruined layer were in the whole sample surface (picture on the right).

